

FOIAb3b

TRANSMITTAL SLIP		DATE
TO: [REDACTED]		
ROOM NO.	BUILDING	
REMARKS:		
<p>Thank you for the attached. I wonder if our current problems with stability of the aircraft with the modified ECM pod and reflection from the pod on System XII are being passed to Colonel Geary for relay to SAC as solutions become apparent or as the problem assumes new dimensions. Please let me know.</p> <p><i>C</i></p> <p><i>MP</i></p>		
FROM: <i>DC</i> <i>SC</i> DAD/OSA		
ROOM NO.	BUILDING	EXTENSION

FOIAb3b

TRANSMITTAL SLIP		DATE
TO: [REDACTED] <i>AM</i>		
ROOM NO.	BUILDING	
REMARKS:		
<p>We would prefer to wait to see if there is any degradation in the "take" which [REDACTED]</p> <p>obtained from a test hop the other day. Also, LAC is to fly 356 with its ECM pods on a long profile mission to further</p>		
FROM:		
ROOM NO.	BUILDING	EXTENSION

FOIAb3b